Serial No.: 10/586,425

AMENDMENT TO THE SPECIFICATION

Please replace the fifth paragraph on page 9 with the following amended paragraph.

The frequency converters, whose extension [[B]] B' does not match the spacing between the two grooves 20 and 22, are each screwed together on the side on the right in Fig. 3 with screws engaging the spring nuts (not represented) introduced into the groove 20. Such a screw is provided with the reference numeral 28 in Fig. 3.